RG104 E-1 Box 158

Mint of the United States at Philadelphia,

Engineer's Office,

July 2. 1889.

Hon. D. M. Fox

Supt. Dear Sir.

The necessary repairs in my department are as follows. Boilers inspected. Boiler feed pumps repaired. main Engines repaired. all valves about the Boilers and Engines repaired. Steam gauges tested and repaired. 3 Dynamos repaired. all joints on Steam pipe renewed. one piece of Steam pipe needed.

Very Respectfully

John Bonner

Chief Engineer

NARA RG104, Entry 1, Box 158

Mint of the United States at Philadelphia,
Engineer's Office,
July 2, 1889

Hon. D.M. Fox
Supt. Dear Sir.

The necessary repairs in my department are as follows. Boilers inspected. Boiler feed pumps repaired. All valves about the Boilers and Engines repaired. Steam gauges tested and repaired. Steam gauges tested and repaired. 3 Dynamos repaired. All joints on steam pipe renewed. One piece of steam pipe needed.

Very Respectfully
John Bonner
Chief Engineer